



January 06



AW55-50SN

K79900N, K7900N, K7900NW/O

We now have available the Main Valve Body Gasket for the above unit (which is bonded to the plate by OE). We are also adding all necessary Nylon Thrust Washers, as well as the Pan Gasket for the Stamped Steel pan*

•	1 pc	79702X	Gasket, Oil Pan (Stamped Seal)
	4		

• 1 pc 79575 Gasket, Main VB Lower

• 1pc 79756 Gasket, Main VB Upper

• 1pc 79851 Thrust Washer, Front Sprag

• 1pc 79852 Thrust Washer, Sprag to Front Hub

• 1pc 79853 Thrust Washer, Rear Sprag

• 2pc 79854 Thrust Washer, Rear Sprag to Drum

*Some units have a Cast Aluminum pan. It is not recommended that a Pan gasket be used in this case.

Please contact your PI Sales Rep or Distributor for more information

Telephone: 631-567-2000
Website: www.transmissionkits.com



Fax: 631-567-2640

e-mail: sales@transmissionkits.com